

## CH-15

No.	Specification	Item	QTY
1	GB/T 818-2000 M4×16	Cross rexxessed pan head tapping screw	2
2	GB/T848-2002 4	cushion	4
3	MAX-15	plastic part	1
4	General	fixed connetion	2
5	30A 85C17-A	ammeter	1
6	K10-2	switch	1
7	KCD-25	power switch	1
8	250V/10A 5x20	power fuse base	1
9	WS/01-MAX-15-04	Front panel	1
10	K10-2	switch	1
11	GB/T 818-2000 M4×25	Cross rexxessed pan head tapping screw	2
12	QL5010 30A	rectifier	1
13	GB/T859-87 4	Spring Cushion	2
14	GB/T6170-2000 M4	Hex nut	2
15	GB/T818 M4×10	Cross rexxessed pan head tapping screw	3
16	188×25×3	belt	1
17	140X25MM	Belt buckle	2
18	WS/01-MAX-15-03	Top cover	1
19	ST4.8×13	Cross rexxessed pan head screw	10
20	WS/01-MAX-15-02	Back panel	1
21	MAX-15	Transformer	1
22	GB/T6170-2000 M5	Hex nut	4
23	GB/T859-87 5	Spring gasket	4
24	GB/T848-2002 5	Cushion	4
25	GB/T 818-2000 M5×16	Cross recessed pan head screw	4
26	Small	Plain washer assemblies	4
27	GB9074.13-88 M4×12	Cross recessed hexagon bolt	2
28	WS/01-MAX-15-01	base	1
29	10A	Accumulator lamp	2
30	3x0.75mm 2x2.4m	power cable	1
31	KCD-25	01 Switch	1

## CH-20

No.	Specification	Item	QTY
-----	---------------	------	-----

1	GB/T 818-2000 M4×16	Cross rexxessed pan head tapping screw	2
2	GB/T848-2002 4	cushion	4
3	MAX-20	plastic part	1
4	General	fixed connetion	2
5	30A 85C17-A	ammeter	1
6	K10-2	switch	1
7	KCD-25	power switch	1
8	250V/10A 5x20	power fuse base	1
9	WS/01-MAX-20-04	Front panel	1
10	K10-2	switch	1
11	GB/T 818-2000 M4×25	Cross rexxessed pan head tapping screw	2
12	QL5010 30A	rectifier	1
13	GB/T859-87 4	Spring Cushion	2
14	GB/T6170-2000 M4	Hex nut	2
15	GB/T818 M4×10	Cross rexxessed pan head tapping screw	3
16	188×25×3	belt	1
17	140X25MM	Belt buckle	2
18	WS/01-MAX-20-03	Top cover	1
19	ST4.8×13	Cross rexxessed pan head screw	10
20	WS/01-MAX-20-02	Back panel	1
21	MAX-20	Transformer	1
22	GB/T6170-2000 M5	Hex nut	4
23	GB/T859-87 5	Spring gasket	4
24	GB/T848-2002 5	Cushion	4
25	GB/T 818-2000 M5×16	Cross recessed pan head screw	4
26	Small	Plain washer assemblies	4
27	GB9074.13-88 M4×12	Cross recessed hexagon bolt	2
28	WS/01-MAX-20-01	base	1
29	10A	Accumulator lamp	2
30	3x0.75mm 2x2.4m	power cable	1
31	KCD-25	01 Switch	1

## CH-30

No.	Specification	Item	QTY
1	GB/T 818-2000 M4×16	Cross rexxessed pan head tapping screw	2
2	GB/T848-2002 4	cushion	4

3	MAX-30	plastic part	1
4	General	fixed connetion	2
5	30A 85C17-A	ammeter	1
6	K10-2	switch	1
7	KCD-25	power switch	1
8	250V/10A 5x20	power fuse base	1
9	WS/01-MAX-30-04	Front panel	1
10	K10-2	switch	1
11	GB/T 818-2000 M4×25	Cross rexxessed pan head tapping screw	2
12	QL5010 50A	rectifier	1
13	GB/T859-87 4	Spring Cushion	2
14	GB/T6170-2000 M4	Hex nut	2
15	GB/T818 M4×10	Cross rexxessed pan head tapping screw	3
16	188×25×3	belt	1
17	140X25MM	Belt buckle	2
18	WS/01-MAX-30-03	Top cover	1
19	ST4.8×13	Cross rexxessed pan head screw	10
20	WS/01-MAX-30-02	Back panel	1
21	MAX-30	Transformer	1
22	GB/T6170-2000 M5	Hex nut	4
23	GB/T859-87 5	Spring gasket	4
24	GB/T848-2002 5	Cushion	4
25	GB/T 818-2000 M5×16	Cross recessed pan head screw	4
26	Small	Plain washer assemblies	4
27	GB9074.13-88 M4×12	Cross recessed hexagon bolt	2
28	WS/01-MAX-30-01	base	1
29	10A	Accumulator lamp	2
30	3x0.75mm 2x2.4m	power cable	1
31	KCD-25	01 Switch	1